



Rectification Report

Building: Building XYZ

Date: 26/05/2015

Address: 123 Sample St

Inspection ID: 5274

Suburb: Sampleton

Sample

Touchwood Fire Doors - Rectification Report

Building XYZ

2/2

No.	Location	Tag	Brand	Dimensions/FRL	Lockset	Closer	Compliant
FD5	L8 Fire Stair		Inglis	2105x840x37			Y
FD14	Ground Floor Fire Stair	5384	Thermador/Masterbilt	2300x1825x45xx1020		Penlux	Y
SD17	Side Reception			2200x940x37			Y
SD17	Side Reception			2200x940x37			Y

Sample

This is a rectification report to QDC, MP 6.1 and A.S. 1851 (2012) on work carried out to the doors listed above. It does not certify that the building is compliant. Smoke doors listed on this report are inspected to BCA requirements as per Specification C3.4.

Work Completed Date: